

REF NO: AA/VVR/2026/006

DATE: 23/03/2026

To,
The Principal / Management,
Rahul International School,
Patankar Park,
Nalasopara (West).

Subject: Structural Audit / Inspection Report of School Building

Dear Sir / Madam,

We thank you for appointing us as consultants for carrying out the structural inspection and preparing the structural audit report of your school building at Patankar Park, Nalasopara (West).

We have carried out a detailed structural inspection of the building, including NDT & visual examination of the external façade as well as internal structural components, to assess the condition of the RCC elements such as columns, beams, slabs, and staircases. The assessment has been conducted through a systematic survey, and the detailed observations are enclosed in the report for your reference.

Based on our inspection, the overall structural condition of the building is found to be satisfactory. The primary load-bearing elements are in sound condition, with no significant structural distress observed. Minor maintenance and repair works are recommended to ensure long-term durability and serviceability of the structure.

Accordingly, the building is classified as:

Category C-3 (Structurally Sound / Safe for Occupancy)


The building is safe for regular use; however, periodic maintenance is advised to preserve its structural health.

Please note that this report is a structural audit document based on visual inspection & NDT and should not be considered as a structural stability certificate.

Thanking you.



Yours faithfully,


Authorized Signatory
Er. Chinmay M. Shinde
TECH. | B.E. (CIVIL) | C.E. | VVCMC PANEL AUDITOR